Accessory Box

The following items are included in the accessory box.

Part	Description	Number	Picture
Ribbon cable/Sensor connector	Cable attached to sensor. Extras are included in the box.	Depends on configuration	
Power cable		1	
Power adapter		1	
USB cable	Used to connect to the computer which has the Assembly Inspection Tool software installed, which is used to test the sensors.	1	

Note: If you need an extender for the USB cable, we recommend the part numbers listed below. We have found that some USB extender cables do not work well.

175-1026-00   USB 2.0, A to A Passive Cable, 5 Meter
933-1295-00   USB Extender over Cat5 for the Multi Touch System